

R/W P.O.B.	Right of way Point of beginning
	Point of commencement
P.C.C.	
R	Radius
ARC	Arc distance
CH	Chord distance
Δ	Delta
C.B.	Chord bearing
•	1/2" Capped iron rod set #7073
<del></del>	Permanent control point set #7073
×	"X" cut in concrete/brick
<b>•</b>	1/2" Iron rod found
A/C	Air conditioning unit
<u> </u>	Backflow preventor
C	Cable equipment
E	Electric équipment
Ħ	Elevator condenser
H	Handhole
E X O Ø	Light pole
0	Manhole
Ð	Meter pole
$\boxtimes$	Metal vent fan
	Sewer cleanout
	Storm grate
$\bowtie$	Water valve
•	- Wood fence

PENSACOLA BY T.C. WATSON (1906); SURVEYS ON FILE WITH THIS FIRM LAND SURVEYOR A BOUNDARY SURVEY AND LOCATION 5700 N. DAVIS HIGHWAY, SUIT PENSACOLA, FL 3 OF IMPROVEMENTS OF A PORTION OF Phone: (850) 434-6666 Fax: (850) 434-6 GRAPHIC SCALE - 1" = 10'Email: pgasurvey@bellsouth. BLOCK 102, WATERFRONT TRACT

<b>S</b> 3			FLO	RIDA	Date of Revision FB <u>I<b>8</b>I</u> O_PG	38-41
<b>503</b> 661	David D. Glaze ■ PSM #5605	Walter J. Glaze	SHEET	OF	FBPG Drawn by	PMJ
;t		PSM #6190 e original seal and original signature of the signing surveyor.	<b>1</b>	1	Checked By	DDG